





- Easy to read and use.
- · Hardwearing.



BRIXOMETER BY GÉRARD TAURIN

5 years Gurantee; Measurement range from 0% to 90%; Supplied in a wooden case.

Item #	ø"	L"	Wt oz.
250128	1 37/64	5 29/32	6.35



REFRACTOMETER

High definition. For checking sugar content expressed in % Brix. Reader Ø 40 mm (1 1/2"). Reference temperature 20°C (68°F), sample temperature 40°C (104°F) maximum. Comes in a protective box.

- 1: Refractometer 0 to 50 %. Precision ± 1 % for sorbets, ice creams, fruit juice concentrates etc.
- 2: Refractometer 58 to 90 %. Precision \pm 0,5 % for jelly, jam, syrups.

	Item #	L"	Wt oz.
1.	250122	5 7/8	5
2.	250124	5 7/8	5



BLOW TORCH

Adjustable flame, electronic ignition, refillable like a lighter. Butane not included.

Item #	W "	L"	Wt
262263	4 1/4	5 3/4	1/2 lb.





- · Very easy to use.
- Digital readout in less than 3 seconds.
- Double Brix/ Baumé scale.

PAL-PÂTISSIER REFRACTOMETER

To precisely monitor sugar content in sorbet, ice cream, jam, ielly Mose, Oto 850 Priv Oto 450 Poumé

jelly. Meas.: 0 to 85% Brix, 0 to 45° Baumé.

Precision: ± 0.2% Brix, ± 1° Baumé. Meas. Temp.: 10°C or 10°F to 40°C or 104°F.

Item #	L"	W "	Н"
250130	4 19/64	1 7/32	2 11/64





1. SUGAR PUMP

Made of rubber and copper. The best pump available for all your blown sugar. Delivered with one copper tip. The air bladder delivers a large volume of air quickly. The wide easy grip hose assures secure handling.

Item #	L"	W "	н"	Wt oz.
262230	14	2.3/8	2	1



2. SUGAR PUMP "ECONOMY"

Made of rubber and copper.

Item #	L"	Copper tip "	Wt oz.
262235	10	5 1/8 long	4



SUGAR SCISSORS

In finely polished stainless steel with black laquered handles.

	Item #	L"	Wt oz.
Ī	072200	9 1/4	8



SUGAR WORK GLOVES

Made of tatex.				
Item #	Size			
262289	S			
262290	М			
262291				